DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor

Kathleen Clarke **Executive Director** Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX	Complete:	Exploration:					
		1 / 1:30 pm -5:00 pm					
Date of Last Inspection: 09/20/2001							

Mine Name: Gordon Creek 2, 7, and 8 Coun	ty: Carbon Permit Number: <u>C/007/016</u>						
Permittee and/or Operator's Name: Mountain Coal Company							
Business Address: <u>HC 35 Box 380, Helper, Utah</u>	84526						
Type of Mining Activity: Underground XXX	Surface Prep. Plant Other						
Company Official(s): Dan Guy							
State Official(s): <u>Joe Helfrich</u> Federal Official(s): <u>None</u>							
Weather Conditions: Sunny, 65							
Existing Acreage: Permitted 2286 Disturbed	20.3 Regraded Seeded						
Status: Active Reclamation XXX							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	П
2.	SIGNS AND MARKERS	[X]	$\overline{\Box}$	[X]	П
3.	TOPSOIL	<u>[X]</u>	$\overline{\Box}$	[X]	П
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	П	\Box		
	b. SEDIMENT PONDS AND IMPOUNDMENTS		\Box	[X]	\Box
	c. OTHER SEDIMENT CONTROL MEASURES	[X] []		П	\Box
	d. WATER MONITORING			П	П
	e. EFFLUENT LIMITATIONS	П	\Box	Ц	П
5.	EXPLOSIVES		[X]	П	
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box	[X]	Ц	
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box	[X]	Ц	П
8.	NONCOAL WASTE	\coprod	[X]	Ц	П
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
	SLIDES AND OTHER DAMAGE	\Box		П	Ц
	CONTEMPORANEOUS RECLAMATION	\Box	\Box		Ц
	BACKFILLING AND GRADING	\Box	[X]	\Box	
	REVEGETATION	\Box	\Box		Ц
	SUBSIDENCE CONTROL	\Box	[X]	Ц	
15.	CESSATION OF OPERATIONS	\Box	[X]	П	\Box
16.	ROADS:				_
	a. CONSTRUCTION/MAINTENANCE/SURFACING		[X]	Ц	Ц
	b. DRAINAGE CONTROLS	\Box	[X]		Ц
	OTHER TRANSPORTATION FACILITIES	\Box	[X]	Ц	Ц
	SUPPORT FACILITIES/UTILITY INSTALLATIONS		[X]	Ц	Ц
	AVS CHECK (4th Quarter- April, May, June)	\Box	[X]	Ц	Ц
	AIR QUALITY PERMIT	П	\Box	Ц	Ц
21.	BONDING & INSURANCE	П	\Box	Ц	Ц

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/016

DATE OF INSPECTION: 10/10/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Applications for phase one bond release, water monitoring changes, and revisions to the reclaimed area are pending.

2. SIGNS AND MARKERS

The identification sign located at the main access at the end of the county road was in good repair.

TOPSOIL 3.

Several photos were taken of the logging road above the permit area. Additional grading could be done to improve the drainage along the road.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

On the day of this inspection, the sediment pond contained a small amount of water from a recent storm.

Inspector's Signature

Date: October 15, 2001

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas &

Mining.

cc:

James Fulton, OSM

Chris Hansen, Canyon Fuel Company Dan Guy, Blackhawk Engineering

Price Field office

O:\007016.GC2\Compliance\2001\P_1010.wpd